Michael O. Leavitt Governor

Robert L. Morgan Executive Director Lowell P. Braxton

Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 telephone (801) 359-3940 fax

(801) 538-7223 TTY www.nr.utah.gov

September 4, 2003

TO:

Minerals File

FROM:

Tom Munson, Senior Reclamation Hydrologist

SUBJECT:

Site Inspection, West Desert Collectors, State Lease ML 41355, S/025/006, Kane

County, Utah

Date of Inspection:

June 25, 2003

Time of Inspection:

10:00 – 11:00 a.m.

Conditions:

Sunny

Participants:

Tom Munson, DOGM

Purpose of Inspection: To confirm the amount of disturbance and the amount of regrading or

reclaimed areas that exist within this permit

Observations:

The area that we call the fence area, which is in the S1/2 of the W1/2 of Section 31, has three areas that have been disturbed but are in various stages of being reclaimed.

The first area visited, "the south area" totaling 1.09 acres, has been reclaimed and appears to be growing good vegetation. The "middle area" consisting of 1.11 acres, has recently been regarded but not seeded by Mr. Loy Crapo. The "north area" still has a small disturbed pit and waste dump totaling about .8 acres. The total of these three areas is 3.0 acres.

The mine related disturbances found in the N1/2 of the W1/2 of section 31 involves two areas. One area is .76 acres, which was recently regarded but not seeded by Mr. Loy Crapo. The regrading work is considered acceptable. Another disturbed area also which was originally attributed to Mr. Caruso's Lease ML-26996, under permit S/025/027, is on Mr. Harris's lease, attributing to an additional .75 acres of unreclaimed disturbance to Mr. Harris's Lease ML-41355. The total disturbance, unregraded, unreclaimed within lease ML 41355 is 1.55 acres.

Conclusions and Recommendations:


It is appropriate that Mr. Harris be aware that he has 1.55 acres of open disturbance and 1.11 acres of regraded area, which is not seeded for a total of 2.62 acres which has not been released within Lease ML-41355. We will consider 1.09 acres reclaimed, as shown on the attached map.

Attachment: GPS map

Robert Harris, operator

Kane\S0250006-tetlaseptarian\inspections\insp-06252003.doc

S/025/006 State Lease - ML 41355 Robert Harris







Site Inspection Date: 6/25/03 Location: W1/2, Section 31

T40 S, R7W

USGS Quadrangle-Orderville(Q1403)

This product may not meet DOGM standards for accuracy and content. Different data sources and input scales may cause some misalignment of data layers.